



Painting and Decorating Contractors of America  
PDCA INDUSTRY STANDARDS

## **PDCA P1-04**

Properly Painted Surface

---

- 2.3. The Painting and Decorating Contractor will produce a **“Properly painted surface.”** A “Proerly painted surface” is defined as uniform in appearance, color, texture, hiding and sheen. It is also free of foreign material, lumps, skins, runs, sags, holidays, misses, or insufficient coverage. It is also a surface free of drips, spatters, spills or overspray caused by the Painting and Decorating Contractor’s workforce. In order to determine whether a surface has been “properly painted” it shall be examined without magnification at a distance of thirty-nine (39) inches or one (1) meter, or more, under finished lighting conditions
-